



SALES - RENTALS - SERVICE - PARTS

569 S. Van Buren Street
Placentia, California 92870
(800) 77-BEJAC • www.bejac.com
Serving All Of The Western United States

20190600

190784

Ship To: CITY OF MARICOPA, AZ

Invoice To: BEJAC RENTAL DEPT
5228 N TOM MURRAY AVE
GLENDALE AZ 85301

IN CASE OF ANY MECHANICAL FAILURE OR ACCIDENT TO THIS EQUIPMENT,
CALL US IMMEDIATELY (800) 772-3522

Branch		
07 - Phoenix AZ		
Date	Time	Page
08/10/2018	16:54:48 (O)	1
Account No.	Phone No.	Invoice No.
BEJAC040		
Ship Via	Purchase Order	
	***QUOTE ONLY**	
Sales Tax Lic. No.		
	Salesperson	
	SRC / BS	

RENTAL CONTRACT

Description CONTRACT #: 007284 Amount

THIS IS A QUOTE ONLY, NOT A CONTRACT

KPTECH DSSHREDDER TDSS CRAMBO 6000 1 MONTH 38400.00
Stock #: Z009398 Serial #: 469109
Date Out: 08/13/2018 07:00 Expected return date: 09/07/2018 07:00
Machine hours out: 218
Rates: 3200.00/DAY 12800.00/WEEK 38400.00/MONTH
O/T Rates Per HR: 400.00/DAY 320.00/WEEK 240.00/MONTH

ADDITIONAL PARTS

LOWBED CHARGE LOWBED Qty: 2 Price: 575.00 1150.00

NON CERT FEE: 5376.00
Subtotal: 44926.00
GLENDALE AZ SALES T: 3532.80
TOTAL RENTAL CHARGE: 48458.80



August 13, 2018

20190614

190785

ATTN: Mike Riggs

PROPOSAL FOR: Pacana Park (Replacement of Storm Damaged Shade Fabric Cover)

PROPOSAL:

Fabricate and install new shade fabric cover on a 60'x77' extreme span structure. Modify structure to provide 12 separate pulley bracket connection points for cable connections at all columns (4,620 Sq. Ft.).

To supply new shade fabric cover, pulley brackets, cables & hardware	\$ 14,385.00
To install pulley brackets & shade fabric cover	\$ 1,920.00
Boom lifts rental charges	\$ 570.00
Sub total	\$ 16,875.00
Maricopa construction services sales tax (6.955%)	\$ 1,173.66
Total	\$ 18,048.66

Lead time: 8 weeks.

Warranty: Shade fabric carries a 10 year pro-rata limited warranty.

SUN PROTECTION - "Commercial 95" - a high density polyethylene shade fabric offers excellent sun protection and blocks up to 98% of harmful UV rays. Because the material is permeable heat is not trapped underneath.

FIRE RATING – E/84 CLASS A – Horizontal NFPA 701.

Should you have any questions or require further information please contact me for prompt attention.

Yours in sun protection,

George Johnson, Shade' N Net



August 6, 2018

20190558

Exe
190721

ATTN: Mike Riggs

PROPOSAL FOR: Copper Sky Park (Repair of Storm Damaged Structure)

PROPOSAL:

Remove damaged shade fabric cover from 58'x92' extreme span structure. Modify structure and shade fabric cover to provide 4 separate pulley bracket connection points for cables at middle columns. Patch holes in cover and reinstall modified cover utilizing new cables and hardware.

To remove damaged cover	\$ 680.00
Boom lift rental charges to remove shade fabric cover	\$ 370.00
To supply 4 pulley brackets & powder coat Bronze (BR-23), new cables & hardware	\$ 1,060.00
To modify & repair shade fabric cover	\$ 470.00
To install pulley brackets & shade fabric cover	\$ 1,460.00
Boom lifts rental charges to install pulley brackets & shade fabric cover	\$ 570.00
Sub total	\$ 4,610.00
Maricopa construction services sales tax (6.955%)	\$ 320.63
Total	\$ 4,930.63

Lead time: 1 week to remove cover and 6 to 8 weeks to install new connection points and reinstall modified/repaired cover.

Should you have any questions or require further information please contact me for prompt attention.

Yours in sun protection,

George Johnson, Shade' N Net